



41A

- Ziarno ścierne: elektrokorund różowy
- Do stępania, wygładzania i wykańczania


Ściernice trzpieniowe

Ściernice trzpieniowe (kształt A)

| Wymiary (mm) D x L | Trzpień (mm) S x L | Kształt | Specyfikacja | Obroty na minutę | Ilość szt./opak. | Nr produktu | Kod EAN 13 |
|--------------------|--------------------|---------|--------------|------------------|------------------|--------------|---------------|
| 20 x 65 | 6 x 40 | A1 | 41A 36 PV | 15000 | 20 | 66243538967 | 8711479165047 |
| 25 x 32 | 6 x 40 | A2 | 41A 36 PV | 20000 | 20 | 66243538973* | 8711479165092 |
| 22 x 70 | 6 x 40 | A3 | 41A 36 PV | 14000 | 20 | 66243538971 | 8711479165085 |
| 22 x 70 | 6 x 40 | A3 | 41A 60 PV | 14000 | 20 | 66243538539 | 8711479164385 |
| 32 x 32 | 6 x 40 | A4 | 41A 36 PV | 17000 | 20 | 66243566869 | 8711479165269 |
| 20 x 28 | 6 x 40 | A5 | 41A 46 PV | 30000 | 20 | 66243538968 | 8711479165054 |
| 20 x 50 | 6 x 40 | A8 | 41A 36 PV | 18000 | 20 | 66243538966 | 8711479165030 |
| 21 x 45 | 6 x 40 | A11 | 41A 36 PV | 18000 | 20 | 66243538969 | 8711479165061 |
| 18 x 30 | 6 x 40 | A12 | 41A 46 PV | 30000 | 20 | 66243538962 | 8711479164972 |
| 25 | 6 x 40 | A25 | 41A 36 PV | 25000 | 20 | 66243538939 | 8711479164804 |
| 16 | 6 x 40 | A26 | 41A 46 PV | 54000 | 20 | 66243538960 | 8711479164941 |
| 30 x 6 | 6 x 40 | A37 | 41A 60 PV | 30000 | 20 | 66243566866 | 8711479165238 |
| 25 x 25 | 6 x 40 | A38 | 41A 36 PV | 25000 | 20 | 66243566862 | 8711479165153 |

* na zamówienie

KSZTAŁTY ŚCIERNIC TRZPIENIOWYCH



Ściernice trzpieniowe (kształt W)



| Wymiary (mm) D x L | Trzpień (mm) S x L | Kształt | Specyfikacja | Obroty na minutę | Ilość szt./opak. | Nr produktu | Kod EAN 13 |
|--------------------|--------------------|---------|--------------|------------------|------------------|-------------|---------------|
| 10 x 13 | 6 x 40 | W176 | 41A 60 PV | 54000 | 20 | 66243538891 | 8711479164101 |
| 10 x 20 | 6 x 40 | W177 | 41A 60 PV | 41000 | 20 | 66243538496 | 8711479164118 |
| 10 x 32 | 6 x 40 | W179 | 41A 60 PV | 25000 | 20 | 66243538943 | 8711479164842 |
| 13 x 20 | 6 x 40 | W186 | 41A 60 PV | 48000 | 20 | 66243538942 | 8711479164835 |
| 13 x 25 | 6 x 40 | W187 | 41A 60 PV | 30000 | 20 | 66243538957 | 8711479164903 |
| 16 x 20 | 6 x 40 | W195 | 41A 46 PV | 47000 | 20 | 66243538893 | 8711479164125 |
| 16 x 25 | 6 x 40 | W196 | 41A 46 PV | 35000 | 20 | 66243538533 | 8711479164354 |
| 16 x 32 | 6 x 40 | SPEC. | 41A 46 PV | 25000 | 20 | 66243538894 | 8711479164132 |
| 20 x 20 | 6 x 40 | W204 | 41A 46 PV | 42000 | 20 | 66243538554 | 8711479164989 |
| 20 x 25 | 6 x 40 | W205 | 41A 46 PV | 32000 | 20 | 66243538896 | 8711479164149 |
| 20 x 32 | 6 x 40 | W206 | 41A 46 PV | 30000 | 20 | 66243538497 | 8711479164156 |
| 20 x 40 | 6 x 40 | W207 | 41A 46 PV | 24000 | 20 | 66243538898 | 8711479164163 |
| 25 x 25 | 6 x 40 | W220 | 41A 36 PV | 25000 | 20 | 66243538899 | 8711479164170 |
| 25 x 40 | 6 x 40 | W221 | 41A 36 PV | 19000 | 20 | 66243538900 | 8711479164187 |
| 32 x 20 | 6 x 40 | W228 | 41A 36 PV | 24000 | 20 | 66243538901 | 8711479164194 |
| 32 x 32 | 6 x 40 | W230 | 41A 36 PV | 17000 | 20 | 66243538503 | 8711479164200 |
| 40 x 13 | 6 x 40 | W236 | 41A 36 PV | 25000 | 20 | 66243566871 | 8711479165283 |
| 40 x 25 | 6 x 40 | W237 | 41A 36 PV | 19000 | 20 | 66243538910 | 8711479164224 |
| 40 x 40 | 6 x 40 | W238 | 41A 36 PV | 12000 | 20 | 66243538510 | 8711479164231 |